Property Inspection Report



123456 Mayberry Lane, Mayberry, Illinois 60001 Inspection prepared for: Steve Savas Real Estate Agent: Best Realtor in the area - Top notch realstate

> Date of Inspection: 11/13/2015 Time: 2:30 pm Age of Home: ~51 years old Size: ~2,000 sq. ft. Weather: 45 degrees and sunny

> > Inspector: Steven P. Savas
> > License #450.010878
> > Phone: 312-315-9797
> > Email: spssav@gmail.com
> > SavasScrutinyHomeInspections.com



Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. All repairs must be done by a licensed &bonded trade or profession. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

| Kitchen | riirig a copy or air re | ceipts, warranties and permits for the work done. |
|-----------------|--------------------------|---|
| | O | . The front left aids burger alid and invite whom tooks a |
| Page 6 Item: 4 | Oven & Range | • The front left side burner did not ignite when tested. |
| Page 6 Item: 5 | Sink | The water pressure appears to be low. I recommend having a licensed plumber evaluate this and correct as needed. |
| Page 7 Item: 7 | Plumbing | The "P" trap under the kitchen sink is installed backwards. I recommend having a licensed plumber evaluate this and repair as needed. |
| Page 8 Item: 8 | Electrical | • The left side of the outlet shows no power or ground. I recommend a licensed electrician evaluate this and repair or replace as necessary. |
| Page 8 Item: 9 | GFCI | • GFCI protected receptacles may not have been required when the house was built. I suggest buyer consider upgrading with GFCI's at all receptacles with in 6 feet of water sources. |
| Laundry | | |
| Page 10 Item: 3 | Electrical | There is a box in the ceiling above the entry door which has exposed wires. This should be covered properly |
| Heat/AC | | |
| Page 11 Item: 3 | AC Compress Condition | The Air conditioning could not be tested because of the exterior temperature being to cold. I would ask the sellers if it works, (especially since the window units have been used and are present.) |
| Page 11 Item: 4 | Filters | Air conditioner blower unit filters are dirty and the ducts are full of dust. I was unable to access and inspect the blower unit in the attic for the air conditioner. Although the fan did turn on when tested. |
| Water Heater | | |
| Page 13 Item: 3 | TPRV | The TPR (Temperature Relief Valve) discharge pipe is incorrect, it should be a hard pipe such as galvanized or copper pipe. |
| Page 13 Item: 4 | Plumbing | There is corrosion occurring on the hot water connection. There should be a dielectric union installed on each side to prevent corrosion. There is a flexible gas supply line to the hot water tank, this typically not code, I recommend checking with the local building department to see if these the village standards. |
| Garage | | |
| Page 15 Item: 3 | Interior Fire Door | • There is no self-closing device on the door from the house leading to the garage. It is strongly recommended that one be installed in order to protect the residence against garage originated fires. |
| Electrical | | |

| avas Scrutiny Hor | me Inspections | 123456 Mayberry Lane, Mayberry, III |
|-------------------|-------------------------|--|
| Page 17 Item: 2 | Breakers | • No.11 circuit is in the off position. It says it is the outlet for the basement sink, which actually is the outlet for the sump pump. I highly recommend a licensed electrician evaluate this to be sure that there is no short and repair as necessary. |
| Page 17 Item: 3 | Miscellaneous | • There is no ground wire connected from the electrical panel to the water supply along with no bridging around from the street side to the domestic side of the water supply. |
| Roof | | |
| Page 18 Item: 4 | Miscellaneous | • The crown on both chimney stacks needs repair. There is rebar showing and cracks are present. This is cause the decay of not only the mortar but the brick as well. |
| Attic | | |
| Page 19 Item: 4 | Insulation Condition | • Insulation that is settled does not perform to the R-Value that it once did. I recommend installing at least 14"-18" of blown in insulation to give an rR-value of R36 or more. |
| Grounds | | |
| Page 22 Item: 3 | Grounds Electrical | There are exposed wires coming from the wall into a an electrical box. This needs to be run in hard pipe. I recommend having a licensed electrician repair or replace this. |
| Page 23 Item: 4 | GFCI | • No Ground Fault Circuit Interrupter (GFCI) protection of home electrical outlets was provided in the home at the time of inspection. Although GFCI protection may not have been required at the time the home was built, for safety reasons, consider upgrading the electrical system to include GFCI protection. |
| Basement | | |
| Page 25 Item: 2 | Basement Electric | • The lights in the crawl space need to be rewired with a hard pipe. A lamp cord is not safe and should not be used. I recommend a licensed electrician evaluate this and repair or replace as needed |
| | | There are two openings in the ceiling that need covers. There is also romex installed. Romex is typically not code, although I would recommend checking with the local building department to see if it is up to code. • There is scorching on the outlet. This is evidence of an overload. This outlet is not designed to be used inside a wall I recommend a licensed electrician remove this outlet and replace or repair as needed. |
| Sump pump/Ejec | tor pumps | |
| Page 27 Item: 1 | Condition | The sump pump does not work. There is no power to the outlet. The sump pump discharge pipe should be of a hard pipe like galvanized or PVC not a flexible hose. The discharge should be directed outside not into the sewer system. There also should be a check valve on the discharge pipe. |

Bedroom 3

Living Room

Page 29 Item: 3

Closets

| The closet light is missing fixture globe. This can be a potential fire hazard if clothing comes in contact with an exposed light bulb. | | | |
|---|-------|--|--|
| | | | |
| Page 2 c | of 39 | | |

| Savas Scrutiny Home Inspections | | 123456 Mayberry Lane, Mayberry, Illin |
|---------------------------------|-----------------|---|
| Page 30 Item: 4 | Fireplace | I recommend having the chimney inspected and swept by a qualified chimney sweep. There is duct tape on the glass which is typically an indication of the damper not sealing properly which allows the cold air to enter the house. |
| Family Room | | |
| Page 34 Item: 3 | Miscellaneous | The light fixture in the closet is missing a globe. |
| Bathroom 3 (seco | ond floor hall) | |
| Page 35 Item: 4 | Plumbing | Illegal flex drain used under kitchen sink. Should be replaced with correct part by licensed plumber. The water pressure to the tub appeared to be very slow. I recommend having a licensed plumber evaluate this and repair as necessary. |
| Bathroom 2 (first | Floor) | |
| Page 36 Item: 2 | GFCI | • I recommend upgrading All receptacle to GFCI protection within 6 feet of all potential wet locations. |

Page 36 Item: 4

Plumbing

• Illegal flex drain used under kitchen sink. Should be replaced with correct part by licensed plumber.

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process. Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFI outlets may not be installed; this report will focus on safety and function, not current code. This report identifies specific noncode, non-cosmetic concerns that the inspector feels may need further investigation or repair. For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

Inspection Details

| 1. Attendance | |
|---|---------|
| In Attendance: Client present • Buyer Agent p | present |
| 2. Home Type | |
| Home Type: Single Family Home | |
| 3. Occupancy | |

Occupancy: Occupied - Furnished

Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

1. Dishwasher

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

2. Garbage Disposal

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | Х |

3. Microwave

| Good | Fair | Poor | N/A | None | |
|------|------|------|-----|------|--|
| Χ | | | | | |

4. Oven & Range

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | Х | | | |
| | | | | |

Observations:

• The front left side burner did not ignite when tested.



5. Sink

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | Χ | | | |

Observations:

• The water pressure appears to be low. I recommend having a licensed plumber evaluate this and correct as needed.



6. Window Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | Х | | | |

Observations:

• The window when unlocked popped open and was very difficult to close. I recommend having the spring evaluated and corrected or replaced as needed. The screen to the same window is torn and shuld be repaire.



7. Plumbing

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | Х | | |

Observations:

• The "P" trap under the kitchen sink is installed backwards. I recommend having a licensed plumber evaluate this and repair as needed.




8. Electrical

| | Good | Fair | Poor | N/A | None |
|---|------|------|------|-----|------|
| ſ | | | | | |
| l | | | ΙX | l | l |
| L | | | | | |

Observations:

• The left side of the outlet shows no power or ground. I recommend a licensed electrician evaluate this and repair or replace as necessary.



9. GFCI

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | Х | |

Observations:

• GFCI protected receptacles may not have been required when the house was built. I suggest buyer consider upgrading with GFCI's at all receptacles with in 6 feet of water sources.



10. Refrigerator

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

11. Miscellaneous

| Good | Fair | Poor | N/A | None | . 🔿 ե |
|------|------|------|-----|------|-------|
| | | | | | מט ן |
| | Х | | | | • T |

oservations: The drawer front is delaminating.



Laundry

1. Cabinets

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | ΙV |
| | | | | ^ |

2. Dryer Vent

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

3. Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | Х | | | |

Observations:

• There is a box in the ceiling above the entry door which has exposed wires. This should be covered properly





4. GFCI

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | ΙV |
| | | l | | ^ |
| | | | | |

5. Plumbing

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

6. Clothes Washer

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| X | | | | |
| | | | | |

7. Clothes Dryer

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Heater Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

2. Venting

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | Х | | | |

Observations:

Tape that shoulld be used on high heat duct is a high heat foil tape.



3. AC Compress Condition

| | Good | Fair | Poor | N/A | None |
|---|------|------|------|-----|------|
| | | | | | |
| | | | | V | |
| | | | | _ ^ | l |
| • | | | | | |

Observations


• The Air conditioning could not be tested because of the exterior temperature being to cold. I would ask the sellers if it works, (especially since the window units have been used and are present.)

4. Filters

| Good | Fair | Poor | N/A | None |
|------|------|-------|-----|------|
| | | | | |
| | | ΙX | l | l |
| | | l · · | ı | l . |

Observations:

Air conditioner blower unit filters are dirty and the ducts are full of dust. I
was unable to access and inspect the blower unit in the attic for the air
conditioner. Although the fan did turn on when tested.



Water Heater

1. Venting

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

2. Water Heater Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

3. TPRV

| Good | Fair | Poor | N/A | None |
|------|------|------------|-----|------|
| | | Х | | |
| | | / \ | | |

Observations:

• The TPR (Temperature Relief Valve) discharge pipe is incorrect, it should be a hard pipe such as galvanized or copper pipe.



4. Plumbing

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | Χ | Х | | |

Observations:

- There is corrosion occurring on the hot water connection. There should be a dielectric union installed on each side to prevent corrosion.
- There is a flexible gas supply line to the hot water tank, this typically not code, I recommend checking with the local building department to see if these the village standards.







Garage

1. Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

2. Exterior Utility Door

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|-------|
| | | | | |
| | | | | lv |
| | | | | 1 ^ 1 |
| | | | | |

3. Interior Fire Door

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | X | Х | | |

Observations:

• There is no self-closing device on the door from the house leading to the garage. It is strongly recommended that one be installed in order to protect the residence against garage originated fires.



4. Garage Door Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Y | | | | |
| _ ^ | | | | |

5. Garage Opener Status

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

6. Garage Door's Reverse Status

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

Observations:

• No eye beam system present. This appears to be an older unit when these safety features were not included with openers.



7. Garage Attic

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

8. Miscellaneous

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|-------|
| | | | | \ \ \ |
| | | l | | ΙX |

Electrical

1. Electrical Panel

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| < | | | | |
| ^ | | | | |


2. Breakers

| Good | Fair | Poor | N/A | None |
|------|------------|------|-----|------|
| | \ <u>/</u> | \ \ | | |
| | X | X | l | |

Observations:

• No.11 circuit is in the off position. It says it is the outlet for the basement sink, which actually is the outlet for the sump pump. I highly recommend a licensed electrician evaluate this to be sure that there is no short and repair as necessary.





3. Miscellaneous

| Good | Fair | Poor | N/A | None |
|------|------|---------------------------------------|-----|------|
| | | , , , , , , , , , , , , , , , , , , , | | |
| | | X | | |

Observations:

• There is no ground wire connected from the electrical panel to the water supply along with no bridging around from the street side to the domestic side of the water supply.



Roof

1. Roof Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| \ \ | | | | |
| X | | | | |

2. Flashing

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

3. Gutter

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

4. Miscellaneous

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | Х | | |

Observations:

• The crown on both chimney stacks needs repair. There is rebar showing and cracks are present. This is cause the decay of not only the mortar but the brick as well.









Attic

1. Ventilation

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

2. Vent Screens

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

3. Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | X |

4. Insulation Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | X | l | |
| | | | | |

Observations:

• Insulation that is settled does not perform to the R-Value that it once did. I recommend installing at least 14"-18" of blown in insulation to give an rR-value of R36 or more.



5. Miscellaneous

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|--------|
| | | | | \ \ |
| | | | | _ ^ |

Exterior Areas

1. Doors

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |
| 1 | | | | |

2. Window Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | Х | | | |

Observations:

Broken glazing observed, suggest re-glazing as necessary.



3. Siding Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

4. Eaves & Facia

5. Exterior Paint

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | Х | | | |

Observations:

Peeling paint observed, suggest scraping and painting as necessary.



Grounds

1. Driveway and Walkway Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | Х | | | |

Observations:

• There is quarry tile missing around the wrought iron. The wrought iron is showing signs of excessive rust.



2. Grading

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

3. Grounds Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | Χ | | |

Observations:

- The door bell does not work.
- There are exposed wires coming from the wall into a an electrical box. This needs to be run in hard pipe. I recommend having a licensed electrician repair or replace this.





4. GFCI

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | ΙV | | l |
| | | ^ | l | |

Observations:

• No Ground Fault Circuit Interrupter (GFCI) protection of home electrical outlets was provided in the home at the time of inspection. Although GFCI protection may not have been required at the time the home was built, for safety reasons, consider upgrading the electrical system to include GFCI protection.



5. Patio

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| ^ | | | | |

6. Deck

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |
| ' ` | | l . | | |

7. Miscellaneous

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | Χ | Х | | |

Observations:

- The knee wall by the deck is showing sign of deterioration. The top is loose and athe wall mortar needs tuckpointing.
- There is mortar missing from the front sill which is causing the mortar to fall out on the stone below. i recommend filling these open areas.
- The shed wood surrounding the upper portion is rotted and should be replaced.
- The fence and gate are in need of some repair.













Basement

1. Plumbing

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

2. Basement Electric

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | Χ | Х | | |

Observations:

• The lights in the crawl space need to be rewired with a hard pipe. A lamp cord is not safe and should not be used. I recommend a licensed electrician evaluate this and repair or replace as needed

There are two openings in the ceiling that need covers. There is also romex installed. Romex is typically not code, although I would recommend checking with the local building department to see if it is up to code.

• There is scorching on the outlet. This is evidence of an overload. This

There is scorching on the outlet. This is evidence of an overload. This
outlet is not designed to be used inside a wall. I recommend a licensed
electrician remove this outlet and replace or repair as needed.









3. GFCI

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | | | V |
| | | l | | _ ^ |
| | | | | |

4. Radon Mitigation

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| ı | | | | l 🗤 |
| | | | | ΙX |
| | | | | l '` |

5. Miscellaneous

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | X | Х | | |

Observations:

- There is water staining under the basement stairs on the foundation wall and on the west wall paneling.
 There are a few cracked glassblock windows









Sump pump/Ejector pumps

1. Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | |
| | | X | l | |

Observations:

• The sump pump does not work. There is no power to the outlet.

The sump pump discharge pipe should be of a hard pipe like galvanized or PVC not a flexible hose. The discharge should be directed outside not into the sewer system.

There also should be a check valve on the discharge pipe.



| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

2. Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

3. Window Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

Bedroom 3

1. Electrical

| G | ood | Fair | Poor | N/A | None |
|---|--------|------|------|-----|------|
| | \ \ | | | | |
| | X | | | | |

2. Window Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

3. Closets

| Good | Fair | Poor | N/A | None | |
|------|------|------|-----|------|----|
| | | | | | ١٧ |
| | | X | l | | • |

Observations:

• The closet light is missing fixture globe. This can be a potential fire hazard if clothing comes in contact with an exposed light bulb.





Living Room

1. Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

2. Window Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

3. Miscellaneous

| Good | Fall | FUUI | IN/A | None |
|------|------|------|------|------|
| | Х | | | |

Observations:

• The closet light is missing a protective globe.




4. Fireplace

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | Х | | | |

Observations:

- I recommend having the chimney inspected and swept by a qualified chimney sweep.
- There is duct tape on the glass which is typically an indication of the damper not sealing properly which allows the cold air to enter the house.





Master Bathroom

| 1 | lectr | ica |
|---|-------|-----|
| | | |

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

2. GFCI

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

3. Exhaust Fan

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

4. Plumbing

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

5. Shower

| Good | Fair | Poor | N/A | None | |
|------|------|------|-----|------|--|
| Х | | | | | |

6. Bath Tubs

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

7. Toilets

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

8. Window

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

Dining Room

1. Electrical

| Good | Fair | Poor | N/A | None | Observations: |
|------|------|------|-----|------|--|
| | | | | | Observations: |
| Х | | | | | • The dimmer switch is missing the knob. |



2. Window Condition

| - | | | · Ola a a a a a fila a a a |
|---|------|------|--|
| ſ | | | ן Observations: |
| | Χ | | • For the age of the windows they are still good windows although they |
| | | | definitely are showing signs of repair and sealing. |



Family Room

1. Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

2. Window Condition

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | Х | | | |

Observations:

- The screen on the patio door is torn.There is a small water stain on the molding to the right of the door.





3. Miscellaneous

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | Χ | | | |

Observations:

• The light fixture in the closet is missing a globe.



Bathroom 3 (second floor hall)

1. Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

2. GFCI

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

3. Exhaust Fan

4. Plumbing

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | Х | | |

Observations:

- Illegal flex drain used under kitchen sink. Should be replaced with correct
- part by licensed plumber.

 The water pressure to the tub appeared to be very slow. I recommend having a licensed plumber evaluate this and repair as necessary.





5. Shower

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

6. Toilet

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| X | | | | |

7. Window

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | Х |

Bathroom 2 (first Floor)

1. Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Χ | | | | |

2. GFCI

| Good | Fair | Poor | N/A | None |
|------|------|----------|-----|------|
| | | V | | |
| | | ^ | | |

Observations:

• I recommend upgrading All receptacle to GFCI protection within 6 feet of all potential wet locations.



3. Exhaust Fan

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| | | | | Х |

4. Plumbing

| | Good | Fair | Poor | N/A | None |
|---|------|------|------|-----|------|
| I | | | Х | | |

Observations:

• Illegal flex drain used under kitchen sink. Should be replaced with correct part by licensed plumber.



5. Toilets

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
| Х | | | | |

Photos




Air Conditioner 2007



Stove 2007



Dishwasher 2007



Refrigerator 2016



Microwave 2006



Water Heater 2007





Furnace 2007

Clothes washer 2007



Clothes Dryer 2007